






INTERFACE DETAILS AND NOTES:

1. APPLICATION SHAFT Ø.375" MINIMUM WHEN USING MAG-H APPLICATION MAGNET. TAP 1/4-20 A MINIMUM DEPTH OF .375".
2. 0.25" SENSOR GAP DISTANCE IS OPTIMAL FOR NORMAL INSTALLATION. THIS IS DEPENDNT ON MOUNT AND MATERIALS.



ISOMETRIC VIEWS
SCALE:NONE

CONFIDENTIAL - ALL RIGHTS RESERVED DISCLOSURE OR DUPLICATION PROHIBITED UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN DECIMAL INCH   MANUFACTURING TOLERANCES .X ±.015 .XX ±.005 .XXX ±.001 ANGLE ±1°	DRAWN: T.WOLFF	DATE: 6/12/2024	 WWW.JORALLC.COM
	CHECKED: A.MINSTER	APPROVED: 6/12/2024	
PART #: PE-30-CUST-ASSY			DESCRIPTION: PE30 INSTALLATION DETAILS
EPICOR #:	REV.	SIZE: B	
			SHEET: 1/1